

Certificate

Chemistry, Microbiology, and Technical Services

CLIENT: Alaskan Copper Works

P. O. Box 3546 Seattle, WA 98124

ATTN : Dale Olsen

Work ID

: Metro Waste Discharge

Taken By : Water

Transported by: Client

: Hand Delivered

SAMPLE IDENTIFICATION:

Sample

Collection

Description

Date

Metro Waste Discharge

05/04/90

Unless otherwise instructed all samples will be discarded on 07/01/90

Respectfully submitted,

Certificate of Analysis

Work Order# : 90-05-102

DATE RECEIVED: 05/07/90 DATE OF REPORT: 05/11/90

CLIENT JOB ID : M14844



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.



Certificate

Chemistry Microbiology, and Technical Services

CLIENT : Alaskan Copper Works

Certificate of Analysis

Work Order # 90-05-102

TESTS PERFORMED AND RESULTS:

Analyte	Units	<u>01</u>
Chromium (Method 218.1)	mg/L	0.22
Copper (Method 220.1)	mg/L	0.13
Nickel (Method 249.1)	mg/L	2.7
Zinc (Method 289.1)	mg/L	0.042



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.